CyberPower®

Before using your new product, please read these instructions to prevent any damage.

USB 3.0 4-Port Hub
CP-H430P Serial **User Guide**

Package contents
• USB 3.0 4-Port Hub
• 5V/3.6A power adapter
• USB cable
• Quick User Guide

System requirements
• Computer with a USB 2.0 or 3.0 port
  Note: USB 3.0 is compatible with USB 2.0, however data transfer speed will be limited to the 2.0 level.
• Latest version of Windows® 8, Windows® 7, Windows Vista®, or Windows® XP; or Mac OS X 10.4 or later

Features
• Backwards compatible with previous-generation USB revisions
• Adds expansion ports with supplemental power to your computer
• Blue LED power indicator
• Supports hot-swappable and Plug & Play capability
• Supports over-current protection at USB host port

Downstream ports (to devices)

LED

Downstream ports (to devices)

Suction cup

Upstream port (to computer)

DC jack (Power connector)

Installation
This USB Hub is a plug and play device. Your computer will display the **Add New Hardware** Wizard after connecting the hub to your computer. Installation may be done whether your computer is powered on or off. It is not necessary to restart your computer after installation.

1. Connect the USB cable to the upstream port on the Hub, then connect the other end of the cable to an unused USB port on your computer.
2. Connect your USB devices to the UBS ports on the Hub.

Self-Powering the Hub:
If additional power is required for connected USB devices, plug the power adapter into the DC jack, then plug the power adapter into a wall outlet.

Specification

FUNCTION		SPECIFICATION
Posts	Downstream	4
	Upstream	1
LED	Power	Blue
Power Mode		Bus Power/Self Power
Output Voltage(per port)		+5V DC
Output Current (per port)		900mA (max)
Operation Temperature		5°C ~ 40°C
Storage Temperature		-20°C ~ 60°C
Humidity		0-80% RH. Noncondensing
Housing		Plastic
Weight		1.51 oz
Dimensions		2.76" x 2.76" x 1.28"

above limitations or exclusions may not apply to you (the Consumer). This limited warranty gives the Consumer specific legal rights and the Consumer may have other rights, which vary from State to State.

To make a Limited Warranty claim:
1. Pack and ship the Hub with a dated Proof-of-Purchase receipt to CyberPower at 4241 12th Ave E, Suite 400, Shakopee, MN 55379;
2. Clearly indicate on the outside of the packaging that this is a WARRANTY RETURN;
3. Clearly include your name and address
    (a) on the outside packaging and
    (b) on a sheet of paper enclosed in the box with the Hub that is being returned; and
4. You MUST prepay all shipping costs and you are responsible for packaging and shipment.

CyberPower will inspect and examine the Hub. If the Hub is defective in material or workmanship, CyberPower will repair or replace it and return it to you at CyberPower's expense at the place you have indicated.

Limited Lifetime Product Warranty

Lifetime Limited Warranty
CyberPower warrants this USB Hub (the Hub) to be free from defect in material or manufacture for its lifetime. If a defect results in product failure during its normal use, CyberPower's sole responsibility is to repair or replace (at its sole option) the Hub.
The foregoing Limited Warranty is the consumer's sole and exclusive remedy and excludes any incidental or consequential damages. Some States do not allow the exclusion or limitation of incidental and consequential damages, so certain of the