

RMCARD205-305 v1.3.5 Release Note

REMOTE MANAGEMENT CARD FIRMWARE RELEASE NOTES

Applicable Products: RMCARD205 / RMCARD305

Version 1.3.5 (Release Date: January 21, 2022)

New Features

- Added a Trap Test command line to the Command Line Interface (CLI).

Feature Improvements

- Improved security by removing the 3DES encryption suite and SHA1 algorithm from SSH Server.
- Added support to the Reset SSL Certificate and SSH Hostkey by removing the jumper from the reset pins when there is a Firmware/Data version mismatch.

Fixes

- Fixes an issue with the RMCARD freezing when users upload a 4096-bit SSH Hostkey.
- Corrects the OID value of the UPS Output Status when UPS is in ECO Mode.
- Resolves an issue with sending email to servers with serve standard.
- Fixes a problem with the Model Name, on the Web Interface, being displayed incorrectly for Three Phase UPS.
- Resolves an issue with displaying the correct outlet username, that includes special characters, in the Outlet User Login/Logout events log.
- Corrects a problem where the changed values aren't displayed accurately after setting a new Subnet Mask and Gateway on the Web Interface.
- Fixes an error where models, that do not support Battery Replacement, will display the UPS Battery Replacement Date field on the Command Line Interface (CLI).