

# PPBE 3.2.3 Release Note

## Bugs Fixed

- In Agent, SNMP Agent Port would be reset to default value if ppbe service was restarted.

## Installer Details

| Product                       | File Name                 | Size (bytes) | MD5 Checksum                     |
|-------------------------------|---------------------------|--------------|----------------------------------|
| Linux 32 bits Installer       | ppbe323-linux-x86.sh      | 165,371,130  | d956f1c621e2eef836d4ec3f7574943b |
| Linux 64 bits Installer       | ppbe323-linux-x86_64.sh   | 159,838,013  | 473a18d0b803f6b4a8c90d6b9b07f80f |
| Mac Installer                 | ppbe323-mac.dmg           | 141,385,728  | f32f49c671835025caf050f274f76981 |
| Windows Installer             | ppbe323-setup.exe         | 159,064,120  | 30ba3c3271723ecb57018327952b629f |
| PPBE Agent Virtual Appliance  | ppbe323_agent_centos.zip  | 515,532,504  | e5ea0d49e404b7a3d68f13ae63dd8641 |
| PPBE Client Virtual Appliance | ppbe323_client_centos.zip | 510,958,216  | ef1bc829ee66cab57b62347ff0099e00 |